



**Vermeer Heartland**  
1600 Heil Quaker Blvd  
La Vergne, TN 37086

To whom it may concern,  
Inspection report for unit Model RTX1250 Serial Number: 1VR6110R081000386

Battery cover missing PN 296296331

A/C: claims not in working condition (blower motor is working)

Few leaks present: leaking under engine and left lift cylinder for rear attachment

Hydraulic tank: sight glass is unreadable

Engine fan: chunks missing, no other cracks found fan may not have current issues

Tracks: right rear has chunks missing

Shoot: both sides are cracked through the weld (common issue) pocket cracking through the welds

Crumber: slightly bent, no fix required at this time

Electrical: Parking brake light, diff lock light, air filter

Sincerely,

**Miguel Lozano**  
Service Writer/Advisor  
Vermeer Heartland Service Department  
(615) 535 0222  
mlozano@vermeerhl.com

**EQUIPPED TO  
DO MORE.®**